

ANNEXURE -II
PROFORM -II (DAMAGED BUILDINGS)
(List of Building inspected and assessed)

Name of the Village : TUNGABHADRA CAMP

Taluk : RAICHUR

Dist: RAICHUR

Sl. No.	Building No.	Whether the building is in		Whether it is Residential or Commercial	Whether the building is under				Name of the Owner / Tenant	Total loss to the building (Rs)	Whether the building is		Compensation Payable (Rs)	Remarks
		Gramathana	Farm		Janata Scheme	Ashraya Scheme	Ambedkar Scheme	Vambe Scheme			Collapsed	Damaged		
1	2	3	4	4(a)	5	6	7	8	9	10	11	12	12(a)	13
1	House	Village	-	Resi	-	-	-	-	Subbaradu S/o Ramanna	20000	Partially	Wall	2000	Rain Water enter into the House
2	House	Village	-	Resi	-	-	-	-	Akbar S/o Sukar Sab	20000	Partially	Wall	2000	Rain Water enter into the House
3	Hut	Village	-	Resi	-	-	-	-	Dhanajay S/o Musalappa	10000	Fully	Hut	2000	Rain Water enter into the House
4	Hut	Village	-	Resi	-	-	-	-	Devendra S/o Musalappa	10000	Fully	Hut	2000	Rain Water enter into the House
5	Hut	Village	-	Resi	-	-	-	-	Mallayya S/o Ramadu	10000	Fully	Hut	2000	Rain Water enter into the House
6	House	Village	-	Resi	-	-	-	-	Sanjeev Ramadu S/o Musalappa	10000	Partially	Wall	2000	Rain Water enter into the House
7	House	Village	-	Resi	-	-	-	-	Gokrappa S/o Narasappa	10000	Partially	Wall	2000	Rain Water enter into the House
8	Hut	Village	-	Resi	-	-	-	-	Shanthappa S/o Yesub	15000	Fully	Hut	2000	Rain Water enter into the House
9	Hut	Village	-	Resi	-	-	-	-	Hussaini S/o Shashappa	15000	Fully	Hut	2000	Rain Water enter into the House
10	House	Village	-	Resi	-	-	-	-	Prabhakar S/o Devayya	20000	Partially	Wall	2000	Rain Water enter into the House
11	Hut	Village	-	Resi	-	-	-	-	Jayamma W/o Narasimha	15000	Fully	Hut	2000	Rain Water enter into the House
12	Hut	Village	-	Resi	-	-	-	-	Ramalingamma W/o Arjunappa	15000	Fully	Hut	2000	Rain Water enter into the House
13	Hut	Village	-	Resi	-	-	-	-	Ramadu S/o Lakshmayya	15000	Fully	Hut	2000	Rain Water enter into the House
14	House	Village	-	Resi	-	-	-	-	Raj Shakar S/o Subbradu	25000	Partially	Wall	3000	Rain Water enter into the House
15	Hut	Village	-	Resi	-	-	-	-	Sunkamma W/o Ranganna	15000	Fully	Hut	2000	Rain Water enter into the House

16	Hut	Village	-	Resi	-	-	-	-	Sudhakar S/o Kamagiri	25000	Fully	Hut	4000	Rain Water enter into the House
17	Hut	Village	-	Resi	-	-	-	-	Eshwrayya S/o Kolapuri	15000	Fully	Hut	2000	Rain Water enter into the House
18	Hut	Village	-	Resi	-	-	-	-	Ramanjinayya S/o Bramayya	15000	Fully	Hut	2000	Rain Water enter into the House
19	Hut	Village	-	Resi	-	-	-	-	Paddamma W/o Devappa	15000	Fully	Hut	2000	Rain Water enter into the House
20	Hut	Village	-	Resi	-	-	-	-	Samuel S/o Narasappa	15000	Fully	Hut	2000	Rain Water enter into the House
21	Hut	Village	-	Resi	-	-	-	-	Jayamma W/o Salman	15000	Fully	Hut	2000	Rain Water enter into the House
22	Hut	Village	-	Resi	-	-	-	-	Babu S/o Bhudappa	15000	Fully	Hut	2000	Rain Water enter into the House
23	Hut	Village	-	Resi	-	-	-	-	Narasimha S/o Nagappa	15000	Fully	Hut	2000	Rain Water enter into the House
												Total	49,000	

Rupees Fourty Nine Thousand Only

1) Name Of Engineer

2) Name of the Offi & sign

3) Name of panchayat Offi & sign

4) Name of house owner/tenant & sign

5) Date of Inspection