ANNEXURE-II

PROFARM-II (DAMAGED BUILDINGS)

(List of buildings inspected and assessed)

Name of the village :- SINGADDINNI

Hobli :- SIRWAR

Sl. No	Buildings No.	Whether the buildings is in		Whether it is residential or Commercial	Whether the buildings is under				Name of the Owner/Tenant	Total loss to the building (Rs.)	whether the building is		Compantation payable (Rs.)
		Gramathana	Farm		Janata scheme	Ashraya scheme	Ambedkar Scheme	Vambe Scheme			collapsed	damaged	
1	2	3	4	4(a)	5	6	7	8	9	10	11	12	12(a)
1	huose	Gramathana	-	Residence	-	-	-	-	gurupadayya s/o amrayya	8000	-	damaged	1500
													3500
2	huose	Gramathana	-	Residence	-	-	-	-	adiveppa s/o virupakshappa	10000	-	damaged	4500
3	huose	Gramathana	-	Residence	-	-	-	-	parvatemma w/o amarappa	8000	-	damaged	1500
													3500
4	huose	Gramathana	-	Residence	-	-	-	-	rama s/o rangappa	10000	-	damaged	2000
5	huose	Gramathana	-	Residence	-	-	-	-	mahadevappa s/o hanumantha	8000	-	damaged	1500
													3500
6	huose	Gramathana	-	Residence	-	-	-	-	budeppa s/o mukkanna	8000	-	damaged	1500
													3500
7	huose	Gramathana	-	Residence	-	-	-	-	linganagouda s/o amaranna gouda	10000	-	damaged	4500
8	huose	Gramathana	-	Residence	-	-	-	-	mallappa s/o siddappa	8000	-	damaged	1500
													3500
9	huose	Gramathana	-	Residence	-	-	-	-	ramangouda s/o sharanappa gouda	8000	-	damaged	1500
													3500
10	huose	Gramathana	-	Residence	-	-	-	-	veresh s/o hampangouda	8000	-	damaged	1500
													3500
11	huose	Gramathana	-	Residence	-	-	-	-	basanagouda s/o mallannagouda	8000	-	damaged	1500
													3500
12	huose	Gramathana	-	Residence	-	-	-	-	mahadevappa s/o hanumantha	10000	-	damaged	2000
13	huose	Gramathana	-	Residence	-	-	-	-	hanumantha s/o tayappa	10000	-	damaged	2000
													55000